## DAIRY AND STREAM CROSSING SURVEY

2016/17 Snapshot



### **KEY POINTS**

**54** A total of 54 dairy farms operating in Marlborough.



**40** farms operate under permitted activity status under the Marlborough Sounds Resource Management Plan.



**14** farms operated under Resource Consent.



**91%** of farms were compliant after follow inspections were completed.



2% of farms were rated technically non-compliant after the follow up inspections.



**7%** of farms were significantly non-compliant after the follow up inspections.

$\sim$	
105	
4242	

83

All farms operating under Resource Consent were compliant this season.

One infringement notice was issued for the ponding of effluent and the discharge of effluent within 20m of a waterway.

### Snapshot of the 2016/17 monitoring programme

# What was found during the 2016/17 inspections and annual monitoring

Marlborough District Council monitored all 54 dairy farms during the 2016/17 survey. Monitoring consists of conducting a site visit to each farm and assessing any records that are required to be provided by resource consent conditions. This season a second compliance report was completed for each farm which assessed the compliance against the Proposed Marlborough Environment Plan (PMEP) rules for dairy shed effluent.

**85%** of farms were rated as compliant after first inspection, this increased to 91% after follow up inspections were completed.

**15%** of farms were assessed as non-complaint, this decreased to 9% after the follow up inspections.

Non-compliance was due to ponding and the discharge of effluent within 20m of a waterway.

Significant non-compliance is due to storage systems being located within 20m of waterway and lack of storage.

### Areas of Non-compliance:

- Ponding of effluent.
- Discharge of effluent
- within 20m of a waterway.
- Storage system located within 20m of a waterway.
- No storage.

### Non-compliance:



Ponding from effluent spread to land.



Effluent spread within 20m of waterway.

### Summary of Compliance Rating System

Results reported in this snapshot reflect the compliance of each permitted activity standard or resource consent condition, the lowest rated condition is the overall compliance level. For example a wastewater discharge consent could have 25 conditions of which 23 are rated compliant (green), 1 is rated minor non-compliance and 1 is rated significant non-compliance – the consent is rated significant non-compliance.

Full	Technical	Environmental non-compliance	Significant
Compliance	non-compliance		non-compliance
100% compliance with all consent conditions/ permitted activity standards assessed	Non-compliance with condition which are considered to only have minor or no adverse environmental effects. E.g. failure to keep records	Breach of effects based/ best practice conditions/ rules that cause minor actual or potential environmental effects. E.g. ponding of wastewater remediated immediately.	Persistent breach of orange grade. Significant breach of effects based/ best practice conditions/ rules that cause actual or potential environmental effects. E.g. multiple exceedances of arameters or wastewater reaching a waterway.



### Compliance Levels over the last three seasons

	2014/2015 Percentage	2014/2015 Percentage	2015/2016 Percentage	2015/2016 Follow up Percentage	2016/2017 Percentage	2016/2017 Follow up Percentage
Full Compliance	70%	77%	73%	91%	85%	91%
Technical non-compliance	N/A	N/A	N/A	N/A	2%	<b>2</b> %
Environmental non-compliance	16%	9%	7%	0%	2%	0%
Significant non-compliance	14%	14%	18%	9%	11%	7%

### **Proposed Marlborough Environment Plan**

The PMEP was notified 9 June 2016;

The discharge of dairy farm effluent into or onto land is a permitted activity within the Rural Environment Zone and the Coastal Environment Zone;

- 7 rules had immediate legal effect;
- 3 have legal effect from 9 June 2019;
- A compliance report for the PMEP rules was completed for each farm this season in order to provide the farmers with an indication of future compliance for the effluent system as it currently operates.

### PMEP Compliance rate for rules with immediate legal effect

Compliance Rating	2016/2017 Percentage	2016/2017 Follow up Percentage
Full Compliance	91%	95%
Technical Non-compliance	0%	0%
Non-Compliance	9%	5%
Significant Non-Compliance	0%	0%

### PMEP from 9 June 2019

- 34 farms will require the storage system to be lined with an
- impermeable material;
- 7 storage systems are located within a Flood Hazard Area;
- 4 farms have discharge fields located within a Soil Sensitive Area;
- A total of 39 farms will be non-compliant if no action is taken to upgrade the current system.

# Stream Crossing Progress Total

- Unfortunately there has been no improvements in eliminating the remaining stream crossings since last season;
- The remaining 21 low priority stream crossings are on eight farms, with 10 crossings being located on one farm;
- The remaining stream crossings have been highlighted to the farmers concerned and plans for elimination have been put in place to be followed up.

### For More Information

For more information on compliance and enforcement monitoring undertaken by Marlborough District Council, contact the Environmental Protection Group Phone: 03 520 7400 Email: monitoring@marlborough.govt.nz Website: www.marlborough.govt.nz

