



26 August 2015

Record No: 15171581
File Ref: H100-004-003-15,
U040217, MFL446,
MPE763
Ask For: Deborah Gihon

New Zealand King Salmon Company
Limited
PO Box 1180
Nelson 7040

Dear Sir/Madam

Marine Farm Inspection - Otanerau Bay, Queen Charlotte Sounds

Marine Farm Site 8396 the resource consent of which is registered to New Zealand King Salmon Company Limited was inspected for compliance on 12 August 2015 at 1312. Below is a table that shows the lights, and marking required for this site and compares that with what is currently on the site.

	Required	Fitted	Operational	Action / Comment
Lights	3	6	6	
Reflective Tape	5	6	6	

It is a condition of your resource consent that your farm is correctly marked and lit, as per the lighting plan issued by the Harbour Master. It is also a requirement under Council's Navigation Bylaws that you must maintain the general state of your farm so that it is not a hazard to navigation.

Yours faithfully

A handwritten signature in black ink, appearing to read 'A. van Wijngaarden', written over a set of horizontal lines.

CAPT. A. VAN WIJNGAARDEN
HARBOUR MASTER

MARINE FARM AUDIT FIELD SHEET				
Site No:	8396	Bay: Q.C.S. Otanerau Bay	Date: 12/8	Time: 1.12 pm
Related Permit/Consents:	U040217, MFL 446, MPE 763			
Audit Team:	Amo, CWH DGI GNE			
Consent Holder/Contact Details:	New Zealand King Salmon Company Limited			
	Required	Fitted	Operational	Action / Comment
Lights	3	16	16	
Radar Reflectors	3	n/a	n/a	
Reflective Tape	5	6	6	
Long-lines	No Constraints # Consented	n/a	n/a	
Identification	4	n/a	n/a	
Orange Buoys	n/a	n/a	n/a	

Additional Comments:

.....


.....

Site 8396



Structures and lighting plan:

Number of Cages



RECEIVED

21 FEB 2006

DISTRICT COUNCIL




Figure 1: Proposed layout of the Otanerau Bay salmon farm (2.0), showing the present position of the farm.

Yellow Springs + Mucke Street

LTV

LTV
RA
RF
ID