

# Project update

20 October 2021

## Kenepuru Road



*Kenepuru Road - view of The Rock site showing the current status*



Drill rig working on site at the Water Tank slip 20.5km from Linkwater



Drill Rig working at slip site 28.5km from Linkwater

Below: We have removed around 4,000 cubic metres of slip material from the slip just before the Mistletoe Bay turn off, and the road width is now reinstated



Before: Mistletoe Bay under slip



After: Mistletoe Bay under slip



At the 12.8km mark from the Linkwater end of Kenepuru Road, the road width has been reinstated by taking the bank back by about 2m and numerous trees have been removed



Approximately 3,000 cubic metres of material has been removed from these slips